

How to Install the Windows Driver

1) For WINDOWS ME, 2000, XP

When connecting the MiniDAB with a PC using the provided USB cable, the driver is automatically installed together with a message "new hardware found."

Clicking [my computer] on PC recognizes the mobile disk in the [my computer] folder.



2) Driver installation method for WINDOWS 98 SE



- ① Go to www.oono.co.uk, download Win98 SE Driver on the C: W of PC.
- ② Double-click the Setupapp.exe file in the downloaded directory as follows.



- ③ Click the "Install"



- ④ Click the "Yes"



- ⑤ When the following window appears then installation is completed, click the "Yes" and then reboot the PC
- ⑥ Once finished the rebooting, connect the PC and the MiniDAB using provided USB CABLE.
- ⑦ When the above process ends, the MiniDAB installation is automatically finished.



- ⑧ Confirm as to whether or not it is recognized as movable disk on My Computer